

Dru BuntinDirector

July 10, 2023

Lake Tishomingo Property Owners Association C/O Mr. Steve Blaha 5699 Tishomingo Road Hillsboro, Missouri 63050

rsblaha@yahoo.com

RE: Lake Tishomingo Dam (MO 30039) Jefferson County

Dear Mr. Blaha:

As a result of an inspection of the Lake Tishomingo Dam on May 31, 2023, I am pleased to inform you that Registration Permit R-156 has been renewed and is enclosed for your use. The term of the permit will be three years from the expiration date of the last registration permit issued for the dam and will expire on July 14, 2026. At that time, the dam will be reinspected by the Dam and Reservoir Safety Program at no cost to you. The permit is being renewed for three years based on the downstream environmental zone classification.

Please refer to the enclosed inspection report and summary for additional information on the inspection. If you have any questions, please feel free to contact Jerry Scheible at (573) 368-2175.

Thanks for your cooperation in renewing this permit.

Sincerely,

MISSOURI GEOLOGICAL SURVEY

Ryan P. Stack, P.E. Chief Engineer Dam and Reservoir Safety Program

RPS/clb Enclosure

STATE OF MISSOURI DEPARTMENT OF NATURAL RESOURCES DAM AND RESERVOIR SAFETY COUNCIL

REGISTRATION PERMIT

Pursuant to Chapters 236.400 through 236.500 of the Revised Statutes of Missouri and the rules established by the Dam and Reservoir Safety Council, and on the basis of an inspection by the Department of Natural Resources for the Lake Tishomingo Dam, Jefferson County, all of which are made a part hereof by reference, **PERMISSION IS HEREBY GRANTED** to Lake Tishomingo Property Owners Association, hereafter known as the permittee, whose address for the purpose of notices and other communications pertaining to this permit is 5699 Tishomingo Road; Hillsboro, Missouri 63050, which address is subject to change by written notice from the permittee, **TO OPERATE** said dam and reservoir located in Section 5, Township 41 North, Range 4 East, having identification number of MO30039, a dam height of 63 feet, a principal spillway elevation of 100.0 feet (site datum), a minimum crest elevation of 108.0 feet (site datum), a reservoir area of 120 acres at the water storage elevation and approximate UTM Coordinates of 4,243,500 Meters North and 709.600 Meters East, Zone 15, subject to the following provisions:

GENERAL PROVISIONS:

- 1. No liability shall be imposed upon or incurred by the State of Missouri and/or the Dam and Reservoir Safety Council, or any of their officers, agents, employees, and members, officially or personally, on account of the granting hereof or on account of any damage to any person or property resulting from any act or omission of the permittee or any of its agents, employees, or contractors, or closed corporations or successors relating to any matter hereunder. This permit shall not be construed as estopping or limiting any legal claim or right of action of the state against the permittee, its agents, employees or contractors for any damages or injury resulting from any such act or omission by them or for violation of or failure to comply with the provisions of the permit or applicable provisions of law.
- 2. The permittee shall comply with all Federal, State and local laws and regulations, and shall obtain such other permits as may be required.

- 3. In cases where the doing by the permittee of anything authorized by this permit shall involve the taking, using or damaging of any property rights or interest of any other person or persons, or of any publicly owned lands or improvements thereon or interests therein, it is the sole responsibility of the permittee, before proceeding therewith, to obtain the written consent of all persons, agencies, or authorities concerned, and to acquire all property, rights and interests necessary therefore, including flood easements or permissions for all properties which may be inundated by the dam on a temporary or permanent basis in the upstream impoundment area below the top of dam elevation.
- 4. The permittee shall notify the Dam and Reservoir Safety Council in writing upon the sale or other transfer of interest in the dam or reservoir.
- 5. Based on conditions existing at the time of issuing this permit, the Downstream Environment Zone is Class II. Future development in the vicinity of the dam and flood plain below the dam may result in a change in classification. This change will necessitate hydraulic and structural upgrading of the dam so the dam is in compliance with the rules and regulations of the Missouri Dam and Reservoir Safety Council. Permittee or its representatives, successors or assigns shall perform any such upgrading upon a change in classification and upon notification from the Missouri Dam and Reservoir Safety Council.
- 6. The permittee shall not alter, enlarge, reduce, repair or remove the dam, reservoir or appurtenances without first obtaining a construction permit from the Dam and Reservoir Safety Council.
- 7. The permittee shall immediately notify in writing, the Chief Engineer of any conditions relating to the structural stability of, hydraulic capacity of, or seepage through the dam discovered during the term of this permit which may differ from those conditions identified in the renewal inspection summary.
- 8. The terms and provisions of this permit shall extend to and bind the successors in authority of the Dam and Reservoir Safety Council and the legally assigned successors in interest of the permittee.
- 9. Maintenance of the dam and reservoir herein permitted shall be the responsibility of the permittee.
- 10. The term of this permit shall be three (3) years from the expiration date of the last registration permit issued for the dam and will expire on July 14, 2026. The permittee shall apply for renewal not less than sixty (60) days prior to this expiration date.

Executed at Rolla, Missouri on this 10^{th} day of July, 2023

DAM & RESERVOIR SAFETY COUNCIL

Ву
Chief Engineer
Dam and Reservoir Safety Program



ID #: MO30039	LAKE TISHOMINGO DAM	INSPECTION DATE: MAY 31, 2023
JEFFERSON COUNTY	PERMIT NUMBER: R-156	HAZARD CLASS: II
EARTHFILL	INSPECTION TEAM: SCHEIBLE/JETT	PLSS: T41NR04ES05

DAM & RESERVOIR SAFETY PROGRAM DAM INSPECTION REPORT

OWNER:	LAKE TISHOMINGO PROPERTY OWNERS ASSOCIATION		
ADDRESS:	C/O MR. STEVE BLAHA, PRESIDENT		
	5699 TISHOMONGO ROAD		
CITY/STATE/ZIP	HILLSBORO, MI	SSOURI 63050	
TELEPHONE:	314-808-4757		
EMAIL:	rsblaha@yahoo.com		
ALTERNATE: CLARUE HOLLAND CELL: 314-623-5869 clarue-martin@att.net			
SPILLWAY TYPE(S):	PRINCIPAL	Concrete weir in rock cut open channel on left abutment	
	AUXILIARY	None	

TABLE OF CONTENTS

Engineer Certification	1
Inspection Checklist	2
Survey and Freeboard Data	3
Inspection Photographs.	3

ENGINEER CERTIFICATION

- ☐ I hereby certify that <u>LAKE TISHOMINGO DAM</u> was inspected in accordance with RSMO 236.400 through RSMO 236.500.
- ☐ I hereby certify that <u>LAKE TISHOMINGO DAM</u> did not have any observed defects that required correction at the time of the inspection.
- ☑ Judgement of Slope Stability The embankment and appurtenant structures appeared to be in good overall condition at the time of the inspection, with no indications of slope instability or excessive seepage.
- ☐ Defects were found that will have to be corrected prior to the permit being renewed.



INSPECTING ENGINEER
Jerry Scheible, PE
Missouri Engineer, PE-2001018805



ID #: MO30039	LAKE TISHOMINGO DAM	INSPECTION DATE: MAY 31, 2023
JEFFERSON COUNTY	PERMIT NUMBER: R-156	HAZARD CLASS: II
EARTHFILL	INSPECTION TEAM: SCHEIBLE/JETT	PLSS: T41NR04ES05

INSPECTION CHECKLIST

ltem	Condition	Issue	Comments
1. Upstream face/riprap	NP		
2. Crest	NP		
3. Downstream face	OR	Uneven surface	Monitor the historic uneven surface of the left 1/3 of the embankment for any changes or movement; such as signs of surficial sliding or scarps.
4. Left groin	NP		
5. Right groin	OR	Seepage	There is evidence of seepage (hydrophitic vegetation and standing water with iron oxidizing bacteria/orange staining) in right groin, approximately 2/3 downslope from the crest. Monitor regularly and if there is any change in color or flowrate, contact the Dam and Reservoir Safety Program.
6. Toe of dam	OR		There is evidence of seepage (wet area) at the toe near the left groin. Monitor regularly and if there is any change in color or flowrate, contact the Dam and Reservoir Safety Program.
7. Principal spillway	NP		
8. Principal spillway outlet	NP		Good job maintaining the vegetation in the channel. Note: the few trees that remain on the channel side walls, upstream of the bedrock drop off, will need to be removed at some point as they grow larger. Recommend to cut and remove before they mature further.
9. Auxiliary spillway	NA		
10. Auxiliary spillway outlet channel	NA		
11. Embankment drains	MR	Vegetation	Clear the excess vegetation from around the outlet pipe to allow proper access and regular visual inspection. (Flow from drain at the inspection was less than 5 gallon/minute.)
12. Lake drain gates/valves	NP		Permanent siphon system
13. Other	NP		

NP = No observable problem EC = Emergency Condition

MR = Maintenance Required **OR** = Observation Required

DO = Defect Observed **NA** = Not Applicable



ID #: MO30039	LAKE TISHOMINGO DAM	INSPECTION DATE: MAY 31, 2023
JEFFERSON COUNTY	PERMIT NUMBER: R-156	HAZARD CLASS: II
EARTHFILL	INSPECTION TEAM: SCHEIBLE/JETT	PLSS: T41NR04ES05


SURVEY and FREEBOARD DATA

STATION	ELEVATION (ft.) ¹	COMMENTS	
TBM	100.0	Temporary benchmark – principal spillway concrete weir	
PS	100.0	Principal spillway inlet	
AS	NA	Auxiliary spillway sill	
Dam	108.0	Low point on crest of dam	
WL	99.9	Water level on day of inspection	
Other	NA	NA	
Available Available		Required	
Freeboard (ft.)	8.0 7.7		

 $^{^1}$ Elevations are based on an assumed, local site datum of 100.0 feet at the temporary benchmark Equipment used \square GPS system \square Auto level and rod

INSPECTION PHOTOS







Downstream face



ID #: MO30039	LAKE TISHOMINGO DAM	INSPECTION DATE: MAY 31, 2023
JEFFERSON COUNTY	PERMIT NUMBER: R-156	HAZARD CLASS: II
EARTHFILL	INSPECTION TEAM: SCHEIBLE/JETT	PLSS: T41NR04ES05



Downstream face- note historic bulge/uneven surface to monitor for change/movement



Principal spillway inlet crest



Principal spillway channel- looking upstream



Principal spillway channel- looking downstream



Seepage area at toe and left groin



Seepage area near right groin



ID #: MO30039	LAKE TISHOMINGO DAM	INSPECTION DATE: MAY 31, 2023
JEFFERSON COUNTY	PERMIT NUMBER: R-156	HAZARD CLASS: II
EARTHFILL	INSPECTION TEAM: SCHEIBLE/JETT	PLSS: T41NR04ES05



Embankment drain pipe outlet- note excess woody vegetation to cut and remove



Siphon system and historic depression to monitor for change